ANNEXURE - I

Project Name:- Health survey of the existing plant structures at IFFCO Paradeep Unit.

Project title:- Inspection report for Condition Assessment of the existing plant structures of FLARE STACK PIPE RACK Structure at AMMONIA PLANT IN OFFSITES & UTILITY At Paradeep, Orissa.

Obs	Distress observed	Length(m)	Section size	Member	Grid No.
				FLARE STACK PIPE RACK	
t corrosion, scaling, pitting on the member, also ir k on RCC pedestal noted.			ISMB 250	Vertical member	A1
t corrosion, scaling, pitting on the member, also ir k on RCC pedestal noted.			ISMB 250	Vertical member	B1
t corrosion, scaling, pitting on the member, also ir k on RCC pedestal noted.			ISMB 250	Vertical member	A2
t corrosion, scaling, pitting on the member, also ir k on RCC pedestal noted.			ISMB 250	Vertical member	B2
t corrosion, scaling, pitting on the member.	S,P		ISMB 200	Longitudinal member	A1-A2
t corrosion, scaling, pitting on the member.	S,P		ISMB 200	Longitudinal member	B1-B2
t corrosion, scaling, pitting on the member.	S,P		ISMB 200	Horizontal member	A1-B1
t corrosion, scaling, pitting on the member.	S,P		ISMB 200	Horizontal member	A2-B2
t corrosion, scaling, pitting on the member.	S,P			Seat and Cleat angle	A1
t corrosion, scaling, pitting on the member.	S,P			Seat and Cleat angle	A2
t corrosion, scaling, pitting on the member.	S,P			Seat and Cleat angle	B1
t corrosion, scaling, pitting on the member.	S,P			Seat and Cleat angle	B2
t corrosion, scaling, pitting on the member.	S,P		ISMB 200	Internal members	A1,A2-B1,B2

Detail description of member to member observation of a FLARE STACK PIPE RACK

Legends:-

SC :- Severe Corrosion

MC :- Medium Corrosion S:- Scaling P:- Pitting WJO:- Weld joint open out NBS:- Nut bolt scaling DPM:- Dust deposition on member

LC :- Light Corrosion

MM:- Member missing NBM:- Nut bolt missing

